



# OCS-A series

## Crane Scale

### OCS-A<sub>1</sub> / A<sub>2</sub>

Model	Capacity	Division	Weight
OCS-1-A	1 ton	0.5 kg	15 kg
OCS-2-A	2 ton	1 kg	15 kg
OCS-3-A	3 ton	1 kg	19 kg
OCS-5-A	5 ton	2 kg	25 kg
OCS-10-A	10 ton	5 kg	49 kg
OCS-15-A	15 ton	5 kg	71 kg
OCS-20-A	20 ton	10 kg	75 kg



- Table Top Scale
- Balance Scale
- Analytical Scale
- Label Printing Scale
- Platform Scale
- Indicator
- Load Cell
- Crane Scale**
- Floor Scale
- Pallet Scale
- Waterproof Scale
- Accessory
- Software
- Medical Scale
- Coin Scale
- Weigh-Bridge
- Moisture Analyzer

Model	OCS-A1	OCS-A2
<b>Display</b>	38mm LED	30mm LCD +Backlight
<b>Face-Board</b>	5 keys keypad	5 keys ABS keypad
<b>Hook</b>	American Standard Rotatable Hook	
<b>Shackle</b>	American Standard Fixed Shackles	
<b>Battery</b>	6V/10Ah Rechargeable Battery	
<b>Remote Controller</b>	Infrared Remote Controller	
<b>Enclosure</b>	Aluminum Die-Casting Case	
<b>Function</b>	Zero, Tare In/Out, Hold Low Voltage Alarm, Battery Supervision, Overload Alarm, Digital Calibration Tare Set, Total/Delete/Clear Total, View Total, Resolution Switch, Auto Off Set, Power-Saving Mode Display Luminance Set, Display Speed Set, Anti-Motion Set, Gravity Acceleration Set	
<b>Accuracy Class</b>	Equivalent To OIML III	
<b>Tare Range</b>	100% F.S.(Full Scale)	
<b>Zero Range</b>	4% F.S.	
<b>Safe Overload</b>	120% F.S.	
<b>Ultimate Overload</b>	400% F.S.	
<b>Overload Alarm</b>	100% F.S.+9e	
<b>Battery Life</b>	More Than 100h	
<b>Temperature Range</b>	-10°C~40°C	

